

Equipment Name:	Paraffin Bath		
Permit To Work Required?	No	Labor	Direct
Safety Procedures Applicable?	No	If "Yes" Give Reference :-	
Store Requisition Reference	N/A	Special Tools	Calibrated Thermometer
Method Approved By :	Date :	Total Estimate Man-Hours	01:00

Item	Job Code	Description of Work	Hrs
1	4112	Carry out the following standard procedure as applicable. i) Check Leads, Fuses and Plugs for serviceability, (mains plugs rewirable type should be opened and terminals checked). ii) Inspect Knobs, Switches and Controls for correct functioning. iii) Inspect for Mechanical Damage. <ul style="list-style-type: none"> • Check with User for faults/problems. • Carry out Electrical Safety Tests. 	
2		Clean bath. b) Fill with distilled water and check temperature control against calibrated thermometer.	
Job Code	4112	Total	
Hours	01:00	To Carry Forward	